
START
SETTING PRESSURE, SOURCE POWER AND BIAS POWER AND FLOWING CHF_3 AND Ar INTO CHAMBER
100
INTRODUCING Cl_2 INTO CHAMBER
102
104
PRECEDING STEPS ARE FINISHED?
NO
YES
COMPLETING SUPPLY OF Cl_2
106
IGNITING PLASMA
108
END

FIG. 1